

Your Electronics Source

Manufacturers' Representative

2539 Cedar Links Drive • Medford, Oregon 97504

Phone (541) 734-4712 • FAX (541) 734-4718

TO Sean Garrett DATE 11/20/97

COMPANY Lowsand, Inc. FROM Jeane Holt

ORDER CONFIRMATION

PER THE FOLLOWING INFORMATION:

PURCHASE ORDER # MECP2A B PURCHASE DATE 11/20/97

PART NUMBER MLC PROTO 2 REV

MANUFACTURER AGASIS

QTY	UNIT COST	EXT. COST	SHIP DATE	TO SHIP VIA	DOCK DATE
25-50	LOT	\$ 1,200.00	11/21/97	FEDX Overnight	11/22/97

Best Available Copy

TOOLING \$ 200.00 TEST \$ 250.00 PHOTO No Charge

IF ANY OF THE ABOVE INFORMATION IS INCORRECT, PLEASE CONTACT Y.E.S.
AS SOON AS POSSIBLE.

YOUR ELECTRONICS SOURCE AND AGASIS
SINCERELY APPRECIATE THIS OPPORTUNITY TO BE OF SERVICE TO YOU.

Exhibit 1 - Pg 1 of 5

1. The first group of respondents (10%) was made up of 100% females, 100% of whom were married. The majority of this group (70%) was aged 40-50 years, 20% were aged 30-40 years, and 10% were aged 50-60 years. The majority of this group (70%) was employed, 20% were unemployed, and 10% were retired. The majority of this group (70%) was a mother, 20% were not a mother, and 10% were both a mother and a father. The majority of this group (70%) was a mother, 20% were not a mother, and 10% were both a mother and a father.

REP FIRM FOR
AGASSIS

REQ. NO. MECP2A	DATE 11/20/97
RESALE NUMBER (IF APPLICABLE) N/A	

TO: YOUR ELECTRONICS SOURCE
2539 CEDAR LINKS DRIVE
MEDFORD, OREGON 97504
(541) 734-4712, FAX (541) 734-4718

SHIP TO: ATT: SEAN GARNETT
SHADOWSAND, INC.
568 LONGVIEW DR
LEXINGTON, KY 40503
(606)277-7208

SHIP VIA: FEDERAL EXPRESS PRIORITY OVERNIGHT SATURDAY DELIVERY	<input checked="" type="checkbox"/> Prepaid <input type="checkbox"/> Collect	F.O.B. POINT: MORGAN HILLS, CA	TERMS: NET 30	DATE REQUIRED IN LEX: 11/22/97
---	---	--	-------------------------	--

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 LOT	PCB # MEC P2A-B, MEC PROTO 2	LOT	1200 00
	FULL BODY GOLD		
	2 DAY TURN (~25-50/LOT)		
1	TOOLING CHARGE		200 00
1	ELECTRICAL TEST		250 00
1	SHIPPING CHARGE FOR FED EX OVERNIGHT SATURDAY DELIVERY		TBD

PLEASE SEND 2 COPIES OF YOUR INVOICE.
Order is to be entered in accordance with prices, delivery, and specifications shown above.
Notify us immediately if you are unable to ship complete order by date specified.

Adams
NC 3811

Purchase Order

Exhibit 1 - Pg. 2 of 5

Sean Garnett (SEAN GARNETT)

AUTHORIZED BY

Your Electronics Source

Manufacturers' Representative

2539 Cedar Links Drive • Medford, Oregon 97504

Phone (541) 734-4712 • FAX (541) 734-4718

QUOTATION

TO Sean Garnett FROM Jeane Holt
 COMPANY Shadowsand, Inc. DATE 11/20/97
 MANUFACTURER AGASIS TIME _____

DESCRIPTION		# OF MFG DAYS	PRICE EACH	EXTENDED PRICE
MPC photo 2				
quoted full body gold	min lot = 25-50	3 days	LOT	\$ 1,000.00
		2 days	LOT	\$ 1,200.00
\$1450				

TOOLING \$ 200.00 ELECTRICAL TEST \$ 250.00 PHOTO No Charge

OTHER:

Handwritten signature/initials

Quotations are based on information available at the time of quote. Any changes to the original information may affect pricing. Acceptance of lead time is subject to shop capacity. Lead time begins after receipt of applicable manufacturing tools and photo plot approvals. Manufacturers liability is limited to the cost of

Exhibit 1-A 3-05

AGASIS

18450 Sutter Blvd.
Morgan Hill, CA 95037
Phone: 408.778.7733
Fax: 408.782.0099
http://www.agasis.com

INVOICE

NO. 0971756-IN
INV. DATE 11/22/97
CUST. NO. SHADO
PAGE: 1

S
O
L
D

T
O

Shadowsand, Inc.
568 Longview Dr.
Lexington

KY 40503

S
H
I
P

T
O

Shadowsand, Inc.
568 Longview Dr.
Lexington

KY 40503

ORDER NUMBER:
ORDER DATE:
SHIP DATE: 11/22/97

CUSTOMER P.O.		SHIP VIA	F.O.B.	TERMS		REP	ORDERED BY	
MECP2A-B		FEDEX		C.O.D.				
ITEM NO.	PART NO. / DESCRIPTION	REV. #	ORDERED	SHIPPED	B/O	PRICE	EXT. AMOUNT	TA
	MEC PROTO 2 (Billed as 1 Lot)		1	1		1,200.00	1,200.00	
	Tooling		30	30			200.00	
	Test						250.00	
SHADOWSAND CHECK # 116								

☐ DISK ☒ ARTWORK ☐ SOLDER SAMPLE ☐ CERTS ☐ CROSS SECTION

☐ OTHER

NET INVOICE: 1,650.00
LESS DISCOUNT: .00
FREIGHT: 29.50
SALES TAX: .00

A 1 1/2% PER MONTH (18% PER ANNUM) SERVICE CHARGE WILL BE ASSESSED ON ALL PAST DUE ACCOUNTS.
MANUFACTURERS LIABILITY IS LIMITED TO THE COST OF THE PRINTED CIRCUIT BOARDS ONLY.

TOTAL DUE:

1,679.50

Exhibit 1 - 12/8/95

AGASIS

18450 Sutter Boulevard
Morgan Hill, CA 95037

Phone (408) 778-7733

Fax (408) 782-0099

Modem (408) 782-0089

CUSTOMER FILM APPROVAL FORM

DATE: 11-20-97 CUSTOMER: SHADOW SAND

PART NUMBER: MEL PROTEC

REV: _____

FILMS PLOTTED

COMPONENT / PRIMARY SIDE ☒

SOLDER / SECONDARY SIDE ☒

PRIMARY SIDE SOLDER MASK ☒

SECONDARY SIDE SOLDER MASK ☒

PRIMARY SIDE LEGEND ☒

SECONDARY SIDE LEGEND ☒

PRIMARY SIDE PASTE MASK ☐

SECONDARY SIDE PASTE MASK ☐

INTERNAL LAYER #4 ☐

INTERNAL LAYER #5 ☐

INTERNAL LAYER #6 ☐

INTERNAL LAYER #7 ☐

INTERNAL LAYER #8 ☐

INTERNAL LAYER #9 ☐

INTERNAL LAYER #10 ☐

INTERNAL LAYER #11 ☐

☒

INT

PHOTOTEC COMMENTS: Top AND Bottom Sides Legend HW

0.003 with when No. 1

PHOTOTEC APPROVAL: GEORGE

DATE: 11-20-97

CUSTOMER COMMENTS / CHANGES REQUIRED

- 1) 0.006" LEGEND LINE WIDTH ~~CHANGE~~ CHANGE IS OK.
- 2) BOTGOLD PLOT IS CORRECT BUT NOT NEEDED, SINCE WE
AGREED TO FULL BODY ~~LEGEND~~ ^{HARD GOLD} PLATING INSTEAD OF SELECTIVE.

APPROVAL: Sam Yoneth

DATE: 11/20/97

FILM APPROVAL FORM MAY BE FAXED TO (408) 782-0099

Exhibit 1 - Pg 5 of 5

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☒ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.